

Water Sample Results for Lead in Drinking Water 2016/2017

 = above action limit of 15 ppb

ND= non detect

ppb= parts per billion

 = resample after flush

sample date	time	building	location	fixture type	result (ppb)	action level (ppb)	Action Taken
10/18/2016	8:45 AM	Allegany	near A1A	sink	ND	15	
10/18/2016	9:07 AM	Allegany	near A2A	sink	ND	15	
10/18/2016	9:10 AM	Allegany	near A3A	sink	ND	15	
10/18/2016	8:50 AM	Allegany	near AGA	sink	ND	15	
10/18/2016	8:47 AM	Allegany	near B1B	sink	ND	15	
10/18/2016	9:00 AM	Allegany	near B2B	sink	ND	15	
10/18/2016	9:14 AM	Allegany	near B3B	sink	3.6	15	
10/18/2016	9:03 AM	Allegany	near C2B	sink	ND	15	
10/18/2016	9:13 AM	Allegany	near C3B	sink	ND	15	
10/18/2016	8:40 AM	Allegany	near RA desk first floor	water fountain	ND	15	
10/18/2016	9:05 AM	Allegany	near tub rm. A2C	water fountain	ND	15	
10/18/2016	9:12 AM	Allegany	near tub room A3C	water fountain	1.1	15	
10/18/2016	8:42 AM	Allegany	near vending area	sink	1.6	15	
10/31/2016	4:00pm	Allegany	RD Apt.-kitchen	sink	ND	15	
11/15/2016	11:44am	Blake	Blake A apt kitchen- 304B	sink	5.5	15	
11/15/2016	11:47am	Blake	Blake A guest restroom 303	sink	14.7	15	flush and resample
12/21/2016	1:15pm	Blake	Blake A guest restroom 303	sink	ND	15	periodic flush &test
11/16/2016	7:30am	Blake	Blake B HW near 104/109	water fountain	ND	15	
11/30/2016	7:21am	Blake	Blake B HW near 208/216	water fountain	2.0	15	
11/30/2016	7:25am	Blake	Blake C HW near 101/116	water fountain	ND	15	
11/16/2016	7:26am	Blake	Blake C HW near 206	water fountain	ND	15	
11/16/2016	7:34am	Blake	Blake C room 3 (sustainab)	sink	4.8	15	
11/1/2016	10:25am	Brodie	204B	sink	16.9	15	flush and resample
12/21/2016	10:30am	Brodie	204B	sink	ND	15	periodic flush &test
11/1/2016	10:27am	Brodie	253B	sink	21.1	15	flush and resample
12/21/2016	10:45am	Brodie	253B	sink	3.8	15	periodic flush &test
11/1/2016	10:35am	Brodie	near 132	water fountain	8.3	15	
11/1/2016	10:10am	Brodie	near 151	water fountain	3.2	15	
11/1/2016	10:12am	Brodie	near 162	water fountain	30.3	15	flush and resample

12/21/2016	10:15am	Brodie	near 162	water fountain	1.5	15	periodic flush &test
11/1/2016	10:36am	Brodie	near 214	water fountain	2.3	15	
11/1/2016	10:22am	Brodie	near 238	water fountain	4.8	15	
11/1/2016	10:30am	Brodie	near 245	water fountain (left.)	4.1	15	
11/1/2016	10:31am	Brodie	near 245	water fountain (rgt.)	2.3	15	
10/6/2016	8:20am	Clark A	HW near rm 118	water fountain	ND	15	
10/25/2016	8:02am	Clark A	Work Control rm 119	sink	ND	15	
10/6/2016	8:13am	Clark B	break room rm 162	sink	ND	15	
10/25/2016	8:06am	Clark B	HW rm 150 next to men's rm	water fountain	ND	15	
10/25/2016	8:09am	Clark B	rm 158 electric shop	sink	3.8	15	
11/4/2016	8:47am	College Union	130	sink	3.5	15	
11/4/2016	9:00am	College Union	321	sink	ND	15	
11/4/2016	8:57am	College Union	350	sink	5.6	15	
11/4/2016	8:56am	College Union	352	sink	7.6	15	
12/23/2016	9:00am	College Union	Fusion Market	3 bay wash sink	ND	15	
12/23/2016	9:03am	College Union	Fusion Market	3 bay wash sink	ND	15	
12/23/2016	9:04am	College Union	Fusion Market	coffee machine	ND	15	
12/23/2016	9:06am	College Union	Fusion Market	ice machine	ND	15	
12/23/2016	9:10am	College Union	Fusion Market	2 bay sink	ND	15	
11/4/2016	8:52am	College Union	left side near 206	water fountain	11.4	15	
11/4/2016	8:45am	College Union	near 104	water fountain	4.4	15	
11/4/2016	9:02am	College Union	near 316	water fountain	5.3	15	
11/4/2016	8:55am	College Union	near 337	water fountain	4.9	15	
11/4/2016	8:50am	College Union	right side near 206	water fountain	4.4	15	
12/23/2016	9:15am	College Union	Starbucks	3 bay wash sink	ND	15	
12/23/2016	9:16am	College Union	Starbucks	ice machine	ND	15	
12/23/2016	9:17am	College Union	Starbucks	cup rinse sink	ND	15	
12/23/2016	9:18am	College Union	Starbucks	cup fountain	4.1	15	
12/23/2016	9:20am	College Union	Starbucks	coffee machine	ND	15	
9/30/2016	7:40am	Erie	HW A Pod rm A1	sink	ND	15	
9/30/2016	7:38am	Erie	HW A Pod rm A2	sink	ND	15	
9/30/2016	7:35am	Erie	HW B Pod rm B3	sink	ND	15	
9/30/2016	7:37am	Erie	HW C Pod rm C2	sink	ND	15	
9/30/2016	7:34am	Erie	HW C Pod rm C3	water fountain	ND	15	

10/5/2016	7:51am	Erie	lounge-kitchen rm A3	sink	ND	15	
10/5/2016	7:58am	Erie	lounge-kitchen rm B1	sink	ND	15	
10/5/2016	7:56am	Erie	lounge-kitchen rm B2	sink	ND	15	
10/5/2016	7:53am	Erie	lounge-kitchen rm C3	sink	ND	15	
10/25/2016	2:18pm	Erie	RD Apt-kitchen	sink	ND	15	
9/30/2016	7:42am	Erie	Rm C04/05	sink	6.5	15	
11/16/2016	8:05am	Erwin	206A	sink	8.3	15	
11/16/2016	8:16am	Erwin	22A	sink	13.1	15	
11/16/2016	8:03am	Erwin	main lobby	water fountain	ND	15	
11/16/2016	8:04am	Erwin	main lobby	water fountain	ND	15	
11/16/2016	8:10am	Erwin	near 218	water fountain	ND	15	
11/16/2016	8:14am	Erwin	near 8	water fountain	1.4	15	
11/15/2016	8:26am	Fraser	3	sink	1.4	15	
11/15/2016	8:34am	Fraser	113C	sink	ND	15	
11/15/2016	8:30am	Fraser	near 119	water fountain	2.4	15	
11/15/2016	8:37am	Fraser	near 215	water fountain	ND	15	
11/15/2016	8:27am	Fraser	near 3	water fountain	ND	15	
10/25/2016	8:36am	Genesee	BG3	sink	2.8	15	
10/25/2016	8:32am	Genesee	near A1A	sink	ND	15	
10/25/2016	8:40am	Genesee	near A2A	sink	ND	15	
10/25/2016	8:50am	Genesee	near A3A	sink	2.6	15	
10/25/2016	8:38am	Genesee	near AGA	sink	11.3	15	
10/25/2016	8:35am	Genesee	near B1B	sink	2.2	15	
10/25/2016	8:44am	Genesee	near B2B	sink	ND	15	
10/25/2016	8:46am	Genesee	near B3B	sink	1.0	15	
10/25/2016	8:42am	Genesee	near C2B	sink	ND	15	
10/25/2016	8:48am	Genesee	near C3B	sink	ND	15	
10/25/2016	8:30am	Genesee	near RA C105	water fountain	ND	15	
10/28/2016	8:50am	Genesee	RD Apt-kitchen BG1	sink	ND	15	
9/30/2016	10:40 AM	Heating Plant	103	water fountain	ND	15	
9/30/2016	10:41 AM	Heating Plant	104	sink	ND	15	
9/29/2026	11:20am	Jones	ARD Apt	sink-kitchen	1.1	15	
9/27/2016	8:33am	Jones	break room rm 39	sink	5.9	15	
9/23/2016	8:59am	Jones	HW near 214	water fountain	3.5	15	

9/23/2016	8:56am	Jones	HW near 241	water fountain	5	15	
9/23/2016	8:53am	Jones	HW near 326	water fountain	5.8	15	
9/23/2016	9:01am	Jones	HW near rm 105	water fountain	3.4	15	
9/23/2016	9:09am	Jones	HW near rm 137	water fountain	3.9	15	
9/27/2016	8:23am	Jones	HW near rm 226	water fountain	5.1	15	
9/23/2016	9:11am	Jones	HW near rm 24	water fountain	12.3	15	
9/27/2016	8:21am	Jones	HW near rm 258	water fountain	23.4	15	to be removed permanently
9/27/2016	8:16am	Jones	HW near rm 341	water fountain	7.1	15	
9/23/2016	8:50am	Jones	HW near rm 359	water fountain	8.9	15	
9/27/2016	8:35am	Jones	HW near rm 38	water fountain	5.4	15	
9/23/2016	8:47am	Jones	HW near rm 459	water fountain	24.3	15	To be replaced with new
9/23/2016	9:03am	Jones	lounge rm 112	sink	10.5	15	
9/27/2016	8:26am	Jones	lounge rm 116	sink	ND	15	
9/23/2016	9:07am	Jones	lounge rm 129	sink	17.1	15	flush and resample
12/21/2016	8:25am	Jones	lounge rm 129	sink	ND	15	periodic flush & test
9/27/2016	8:20am	Jones	lounge rm 250	sink	2.8	15	
9/27/2016	8:29am	Jones	men's rm 4	sink	2.6	15	
9/27/2016	8:13am	Jones	women's rm 304	sink	1.5	15	
10/28/2016	7:42am	Lauderdale	kitchen rm 214	sink- island	1.9	15	
10/25/2016	7:31am	Lauderdale	Kitchen sink next to wall rm 214	sink	2.6	15	
10/25/2016	7:33am	Lauderdale	main lobby rm 102	water fountain	1.7	15	
11/14/2015	3:12pm	Lauderdale	rm 214	ice machine	ND	15	
9/23/2016	8:18am	Livingston	HW near 341	water fountain	1.8	15	
9/23/2016	8:30am	Livingston	HW near rm 137	water fountain	ND	15	
9/23/2016	8:38am	Livingston	HW near rm 137	water fountain	ND	15	
9/27/2016	8:02am	Livingston	HW near rm 152	water fountain	37.2	15	to be removed permanently
9/23/2016	8:23am	Livingston	HW near rm 214	water fountain	ND	15	
9/23/2016	8:35am	Livingston	HW near rm 24	water fountain	1.4	15	
9/27/2016	7:48am	Livingston	HW near rm 241	water fountain	ND	15	
9/27/2016	7:43am	Livingston	HW near rm 314	water fountain	1.1	15	
9/27/2016	7:40am	Livingston	HW near rm 326	water fountain	1.4	15	

9/27/2016	7:55am	Livingston	HW near rm 39A	water fountain	ND	15	
9/23/2016	8:28am	Livingston	lounge rm 129	sink	8.2	15	
9/23/2016	8:21am	Livingston	lounge rm 250	sink	1.4	15	
10/25/2016	7:24am	Livingston	lounge-kitchen rm 112	sink	1.3	15	
9/27/2016	7:46am	Livingston	men's rm 224	sink	ND	15	
9/23/2016	8:14am	Livingston	men's rm 455	sink	1.1	15	
10/5/2016	8:00am	Livingston	RD Apt-kitchen	sink	ND	15	
9/23/2016	7:40am	Livingston	women's rm 253	sink	4.4	15	
9/23/2016	7:42am	Livingston	women's rm 355	sink	ND	15	
12/23/2016	8:25am	Mary Jemison	2nd fl, 100, deli	soda fountain	ND	15	
12/23/2016	8:27am	Mary Jemison	2nd fl, 100, deli	ice machine	ND	15	
12/23/2016	8:28am	Mary Jemison	2nd fl, 100, deli	3 bay wash sink	ND	15	
12/23/2016	8:21am	Mary Jemison	ground fl, 1, main dining	water fountain	ND	15	
12/23/2016	8:11am	Mary Jemison	ground fl, 2	soda fountain #2	ND	15	
12/23/2016	8:09am	Mary Jemison	ground fl, 2 southern most	soda fountain	ND	15	
12/23/2016	8:13am	Mary Jemison	ground fl, 2, east wall	3 bay wash sink	2.3	15	
12/23/2016	8:19am	Mary Jemison	ground fl, 2, sushi	sink	1.6	15	
12/23/2016	8:19am	Mary Jemison	ground fl, 2, sushi	coffee machine, left	1.4	15	
12/23/2016	8:17am	Mary Jemison	ground fl, 3, dish room	suspended spring faucet,	ND	15	
12/23/2016	8:02am	Mary Jemison	ground fl, main kit, 11	3 bay wash sink	1.7	15	
12/23/2016	8:04am	Mary Jemison	ground fl, main kit, 11	coffee machine	ND	15	
12/23/2016	8:07am	Mary Jemison	ground fl, main kit, 11	ice machine	ND	15	
11/1/2016	11:13am	Merritt	athletic office opposite 216	water fountain	2.3	15	
11/1/2016	11:14am	Merritt	athletic office rm. 232	sink	4.1	15	
11/2/2016	9:30am	Merritt	locker rm. 144	water fountain	7.4	15	
11/1/2016	11:03am	Merritt	men's locker room 157A	water fountain	1.2	15	
11/1/2016	10:48am	Merritt	near 108	water fountain	ND	15	
11/1/2016	10:47am	Merritt	near 115	water fountain	ND	15	
11/1/2016	10:45am	Merritt	near 208	water fountain	1.1	15	
11/1/2016	11:10am	Merritt	pool area east	water fountain	ND	15	
11/1/2016	11:00am	Merritt	women's locker room 147A	water fountain	1.5	15	
11/1/2016	10:49am	Merritt	work out center	water fountain	1.0	15	
12/23/2016	8:38am	Milne	2nd fl, books & bytes, 203	3 bay wash sink	1.0	15	
12/23/2016	8:37am	Milne	2nd fl, books & bytes, 203, left	coffee machine	ND	15	

9/30/2016	9:33am	Milne	3rd floor (only one present)	water fountain	1.5	15	
9/30/2016	7:52am	Milne	books & bytes ADA fountain	water fountain	ND	15	
10/6/2016	7:45am	Milne	rm 113- bottle filler	water fountain	ND	15	
9/30/2016	9:30am	Milne	staff break rm 103B	sink	8.3	15	
9/30/2016	7:54am	Milne	staff break rm 211/212	sink	2.2	15	
10/6/2016	7:41am	Milne	staff break rm 211/212	water fountain	16.2	15	flush and resample
12/21/2016	8:00am	Milne	staff break rm 211/212	water fountain	ND	15	periodic flush &test
10/28/2016	8:11am	Nassau	HW at main Lobby	water fountain	2.0	15	
10/28/2016	8:08am	Nassau	HW near 309	water fountain	5.4	15	
10/25/2016	7:52am	Nassau	HW near laundry room	water fountain	2.6	15	
10/25/2016	7:54am	Nassau	HW near suite 109	water fountain	3.2	15	
10/25/2016	7:48am	Nassau	HW near suite 209	water fountain	ND	15	
10/25/2016	7:44am	Nassau	HW near suite 300	water fountain	1.3	15	
10/28/2016	8:13am	Nassau	kitchen bottom fl near 119	sink	45.5	15	flush and resample
12/21/2016	11:05am	Nassau	kitchen bottom fl near 119	sink	ND	15	periodic flush &test
10/5/2016	11:10am	Nassau	RD Apt-kitchen	sink	ND	15	
9/30/2016	7:46am	Newton	HW near men's rm	water fountain	3.3	15	
10/6/2016	7:50am	Newton	HW near rm 204 (space 222)	water fountain	ND	15	
9/30/2016	7:49am	Newton	HW near rm 214	water fountain	ND	15	
10/28/2016	8:29am	Niagara	HW near 213	water fountain	ND	15	
10/28/2016	8:26am	Niagara	HW near 313	water fountain	ND	15	
10/28/2016	8:22am	Niagara	HW near 409	water fountain	ND	15	
10/28/2016	8:37am	Niagara	kitchen ground fl near 119	sink	2.1	15	
11/15/2016	7:31am	Niagara	near rm 109	water fountain	ND	15	
11/15/2016	7:28am	Niagara	near rm 209/230	water fountain	ND	15	
11/15/2016	7:26am	Niagara	near rm 309/330	water fountain	ND	15	
11/15/2016	7:24am	Niagara	near rm 413/426	water fountain	ND	15	
10/31/2016	7:45am	Niagara	RD Apt-kitchen	sink	ND	15	
10/28/2016	9:17am	Onondaga	115	sink	ND	15	
10/28/2016	9:00am	Onondaga	near 213	water fountain	ND	15	
10/28/2016	9:20am	Onondaga	near 236 (north)	bottle station	ND	15	
10/28/2016	9:22am	Onondaga	near 277 (north)	water fountain	ND	15	
10/28/2016	9:05am	Onondaga	near 340 (south)	water fountain	ND	15	
10/28/2016	9:03am	Onondaga	near 342 (south)	water fountain	ND	15	

10/28/2016	9:25am	Onondaga	near 427 (north)	water fountain	ND	15	
10/28/2016	9:10am	Onondaga	near 431 (south)	water fountain	ND	15	
10/28/2016	9:08am	Onondaga	near 441 (south)	water fountain	ND	15	
10/28/2016	9:15am	Onondaga	near stairwell 101 (south)	water fountain	ND	15	
10/28/2016	9:34am	Onondaga	RD Apt-221 (south)	sink	ND	15	
9/30/2016	10:12 AM	Ontario	near A1B	sink	ND	15	
9/30/2016	10:25 AM	Ontario	near A2B	sink	ND	15	
9/30/2016	10:27 AM	Ontario	near A3B	sink	ND	15	
9/30/2016	10:10 AM	Ontario	near AGB	sink	ND	15	
9/30/2016	10:16 AM	Ontario	near B1A	sink	ND	15	
9/30/2016	10:18 AM	Ontario	near B2A	sink	ND	15	
9/30/2016	10:30 AM	Ontario	near B3A	sink	ND	15	
9/30/2016	10:06 AM	Ontario	near BG5	sink	1.3	15	
9/30/2016	10:14 AM	Ontario	near C105	water fountain	ND	15	
9/30/2016	10:23 AM	Ontario	near C2C	sink	ND	15	
9/30/2016	10:32 AM	Ontario	near C3C	sink	ND	15	
9/30/2016	10:20 AM	Ontario	near tub rm. O2C	water fountain	ND	15	
10/28/2016	10:10am	Ontario	RD Apt-BG6	sink	ND	15	
12/2/2016	7:29am	Schrader	HW near closed pool rm 115	water fountain	ND	15	
12/2/2016	7:31am	Schrader	HW near rm 1-across from men's	water fountain	ND	15	
11/30/2016	7:30am	Schrader	HW outside gym/fac planning near	water fountain	15.0	15	flush and resample
12/21/2016	11:20am	Schrader	HW outside gym/fac planning near	water fountain	10.7	15	periodic flush &test
12/2/2016	7:43am	Schrader	HW outside of raq courts, space 64.	water fountain	3.3	15	
11/30/2016	8:09am	Schrader	HW outside of raq courts, space 64.	water fountain	1.3	15	
11/30/2016	8:05am	Schrader	HW outside of rm 1/4 (porcelain)	water fountain	7.4	15	
11/30/2016	7:34am	Schrader	Ice Machine-outside of women's	Ice Machine	ND	15	
11/30/2016	7:49am	Schrader	men's locker room, 39 eastern (right)	sink	5.7	15	
11/30/2016	7:47am	Schrader	men's locker room, 40 right most	sink	2.1	15	
12/2/2016	7:26am	Schrader	off gym: in mid building stairwell to	water fountain	1.9	15	
12/2/2016	7:38am	Schrader	UPD breakroom (rm 46)	sink	3.4	15	
12/2/2016	7:41am	Schrader	UPD ladies break/rest rm	sink	2.0	15	
11/30/2016	7:39am	Schrader	women's locker room, 114	water fountain	3.0	15	
11/15/2016	7:55am	South Hall	104	sink	ND	15	
11/15/2016	8:04am	South Hall	216	sink	ND	15	

11/15/2016	8:17am	South Hall	319	sink	1.8	15	
11/15/2016	8:00am	South Hall	119A	sink	ND	15	
11/15/2016	8:23am	South Hall	322B	sink	ND	15	
11/15/2016	7:57am	South Hall	near 126	water fountain	ND	15	
11/15/2016	8:06am	South Hall	near 200	water fountain	ND	15	
11/15/2016	8:07am	South Hall	near 239	water fountain	ND	15	
11/15/2016	8:14am	South Hall	near 300	water fountain	ND	15	
11/15/2016	8:13am	South Hall	near 341	water fountain	ND	15	
9/30/2016	9:17am	Steuben	AC Apt	sink-kitchen	3	15	
9/27/2016	8:56am	Steuben	HW near rm B126	water fountain	4.6	15	
9/27/2016	8:52am	Steuben	HW near rm D229	water fountain	6.6	15	
9/27/2016	8:46am	Steuben	HW near rm A210	water fountain	6.9	15	
9/27/2016	8:44am	Steuben	HW near rm A310	water fountain	7.4	15	
9/27/2016	8:48am	Steuben	HW near rm B230	water fountain	65	15	To be replaced with new
9/23/2016	9:25am	Steuben	HW near rm B330	water fountain	3.3	15	
9/27/2016	8:50am	Steuben	HW near rm C211	water fountain	11.4	15	
9/23/2016	9:28am	Steuben	HW near rm D328	water fountain	2	15	
9/23/2016	9:49am	Steuben	lounge-kitchen near A112	sink	ND	15	
9/23/2016	9:36am	Steuben	lounge-kitchen near C211	sink	ND	15	
9/23/2016	9:46am	Steuben	men's rm near A106	sink	1.1	15	
9/23/2016	7:53am	Steuben	rm B239	sink	1.7	15	
9/23/2016	7:55am	Steuben	women's rm near C314	sink	ND	15	
9/23/2016	7:59am	Steuben	women's rm near C414	sink	1.7	15	
9/23/2016	9:39am	Steuben	zone sink near C206	sink	ND	15	
11/15/2016	7:42am	Sturges	HW near rm 103	water fountain	3.7	15	
10/28/2016	7:57am	Sturges	HW near rm 17	water fountain	1.0	15	
10/28/2016	7:52am	Sturges	HW near rm 213	water fountain	4.2	15	
10/28/2016	7:49am	Sturges	HW near rm 314	water fountain	37.5	15	to be removed permanently
12/21/2016	9:40am	Sturges	HW near rm 314 after 1st flush	water fountain	18.1	15	see above

1/27/2017	7:50am	Sturges	HW near rm 314 3rd floor after 2nd flush	water fountain	46.3	15	see above
10/28/2016	8:00am	Sturges	rm 31	sink	55.8	15	flush and resample
12/21/2016	8:40am	Sturges	rm 31	sink	4.9	15	periodic flush & test
10/28/2016	7:55am	Sturges	room 121 kitchen AOP	sink	31.9	15	flush and resample
12/21/2016	8:55am	Sturges	room 121 kitchen AOP	sink	6.9	15	periodic flush & test
11/15/2016	7:44am	Sturges	room 13G	sink	2.8	15	
11/15/2016	7:38am	Sturges	room 205	sink	7.8	15	
9/30/2016	7:28am	Suffolk	HW near rm 123	water fountain	5.5	15	
10/5/2016	7:37am	Suffolk	HW near rm 204	water fountain	23.6	15	to be removed permanently
9/30/2016	7:25am	Suffolk	HW near rm 214	water fountain	6.1	15	
9/30/2016	7:26am	Suffolk	HW near rm 230 (fr. entrance)	water fountain	ND	15	
10/5/2016	7:35am	Suffolk	HW near rm 304	water fountain	1.2	15	
9/30/2016	7:23am	Suffolk	HW near rm 314	water fountain	2.1	15	
9/30/2016	7:20am	Suffolk	HW next to rm 404	water fountain	3.5	15	
10/5/2016	7:40am	Suffolk	lounge-kitchen rm 120	sink	2	15	
10/6/2016	8:04am	Suffolk	RD Apt-kitchen	sink	6.3	15	
9/30/2016	7:29am	Suffolk	rm 126	sink	4.2	15	
11/16/2016	7:55am	Wadsworth	103	water fountain	7.5	15	
11/16/2016	8:00am	Wadsworth	201	water fountain	3.2	15	
11/16/2016	7:50am	Wadsworth	near 21	water fountain	ND	15	
11/16/2016	7:51am	Wadsworth	near 21	water fountain	2.6	15	
10/25/2016	9:00am	Wayne	101	sink	ND	15	
10/25/2016	9:02am	Wayne	opposite 102	water fountain	ND	15	
10/25/2016	9:05am	Wayne	opposite 213	water fountain	ND	15	
10/25/2016	9:07am	Wayne	opposite 303	water fountain	ND	15	
10/25/2016	9:10am	Wayne	opposite 403	water fountain	ND	15	
11/4/2016	9:17am	Welles	near 119	water fountain	ND	15	

11/4/2016	9:18am	Welles	near 134	water fountain	2.3	15	
11/4/2016	9:20am	Welles	near 213	water fountain	ND	15	
11/4/2016	9:23am	Welles	near 227	water fountain	ND	15	
11/4/2016	9:22am	Welles	near 232	water fountain	ND	15	
11/4/2016	9:15am	Welles	print shop near 13E	sink	ND	15	
10/18/2016	9:22 AM	Wyoming	AGA1	sink	4.1	15	
10/18/2016	9:25 AM	Wyoming	near A1B	sink	ND	15	
10/18/2016	9:35 AM	Wyoming	near A2B	sink	ND	15	
10/18/2016	9:40 AM	Wyoming	near A3B	sink	ND	15	
10/18/2016	9:27 AM	Wyoming	near B1A	sink	ND	15	
10/18/2016	9:30 AM	Wyoming	near B2A	sink	1.1	15	
10/18/2016	9:45 AM	Wyoming	near B3A	sink	ND	15	
10/18/2016	9:32 AM	Wyoming	near C2C	sink	ND	15	
10/18/2016	9:42 AM	Wyoming	near C3C	sink	ND	15	
10/18/2016	9:43 AM	Wyoming	near tub room A3B	water fountain	1.4	15	
10/18/2016	9:26 AM	Wyoming	near vending area 1st floor	sink	5.9	15	